


a jövő viselete...

1. Charge the battery of the vest until the charger light turns green. The charging time of an empty battery usually is 4-6 hours.
2. Carefully connect the fully charged battery to the vest.



3. Activate (and deactivate) the vest by pressing the ON/OFF button for at least 3 seconds.
4. Select the desired heating mode by pressing the button 1x time quickly.
5. The color of the button indicates the heating level that is set. Red (High), Blue (Medium), Green (Low).
6. 4 small LED-lights of the button indicate the current battery capacity that is left.

MAGYAR

1. Töltse a mellény akkumulátorát addig, amíg a töltő zöldre nem vált. Egy üres akkumulátor töltési ideje általában 4-6 óra.
2. Óvatosan csatlakoztassuk a töltőt a mellényhez.
3. Kapcsolja be (és kapcsolja ki) a mellényt az ON/OFF gomb legalább 3 másodperces megnyomásával.
4. Válassza ki a kívánt fűtési módot a gomb egyszeri gyors megnyomásával.
5. A nyomógomb színe mutatja a beállított fűtési fokozatot. Piros (magas hőfok) 65 fok, Kék (közepes hőfok) 55 fok, Zöld (alacsony hőfok) 45 fok
6. A nyomógombon található 4 kicsi Led fény mutatja az akkumulátor aktuális töltöttségi szintjét.